```
E I DUPONT -- DELRIN ACETAL RESIN, 550SA NC010
MATERIAL SAFETY DATA SHEET
NSN: 801000N015404
Manufacturer's CAGE: 18873
Part No. Indicator: A
Part Number/Trade Name: DELRIN ACETAL RESIN, 550SA NC010
______
                        General Information
______
Company's Name: E. I. DUPONT DE NEMOURS & CO INC
Company's Street: 1007 MARKET STREET Company's City: WILMINGTON
Company's State: DE
Company's Country: US
Company's Zip Code: 19898
Company's Emerg Ph #: 800-441-3637;800-424-9300(CHEMTREC)
Company's Info Ph #: 800-441-7515
Record No. For Safety Entry: 001
Tot Safety Entries This Stk#: 001
Status: SMJ
Date MSDS Prepared: 21DEC88
Safety Data Review Date: 24MAY95
MSDS Preparer's Name: J B ARMITAGE
Preparer's Company: SAME MSDS Serial Number: BKQCY
Hazard Characteristic Code: N1
______
                 Ingredients/Identity Information
______
Proprietary: NO
Ingredient: POLYOXYMETHYLENE, POLYACETAL
Ingredient Sequence Number: 01
CAS Number: 9002-81-7
OSHA PEL: NOT APPLICABLE
ACGIH TLV: NOT APPLICABLE
Proprietary: NO
Ingredient: ADDITIVES; ANTIOXIDANTS, LUBRICANTS AND STABILIZERS. Ingredient Sequence Number: 02
OSHA PEL: NOT APPLICABLE
ACGIH TLV: NOT APPLICABLE
______
                 Physical/Chemical Characteristics
______
Appearance And Odor: GRANULES OR POWDER WITH SLIGHT FORMALDEHYDE ODOR. Melting Point: 342F,172C
Specific Gravity: 1.42
Solubility In Water: INSOLUBLE Percent Volatiles By Volume: N/A
______
                 Fire and Explosion Hazard Data
 Flash Point: 612F,322C
Extinguishing Media: WATER, CO*2, FOAM, DRY CHEMICAL.
Special Fire Fighting Proc: USE NIOSH/MSHA APPROVED SCBA AND FULL PROTECTIVE EQUIPMENT (FP N) FOR PROTECTION FROM FUMES OF FORMALDEHYDE.
Unusual Fire And Expl Hazrds: BURNS WITH A COLORLESS FLAME. DELRIN DUST
CLOUD IGNITION TERMPERATURE 440C.
______
                          Reactivity Data
______
Cond To Avoid (Stability): HEATING ABOVE 230C - FORMS FORMALDEHYDE.
Materials To Avoid: STRONG ACIDS AND BASES (DECOMPOSES FORMING
FORMALDEHYDE). STRONG OXIDIZING AGENTS.
Hazardous Decomp Products: CO & FORMALDEHYDE. FORMALDEHYDE IS CLASSIFIED AS AN ANIMAL CARCIN, & HAS AN OSHA PERMISSIBLE EXPOS LIMIT OF (SUPP DATA) Conditions To Avoid (Poly): NONE SPECIFIED BY MANUFACTURER.
______
                        Health Hazard Data
______
LD50-LC50 Mixture: NONE SPECIFIED BY MANUFACTURER.
Route Of Entry - Inhalation: NO Route Of Entry - Skin: NO
Route Of Entry - Ingestion: NO
Health Haz Acute And Chronic: (ACUTE) INGEST: NOT A PROBABLE ROUTE OF EXPOSURE. SKIN: NOT TOXIC. HOT POLYMER WILL CAUSE THERMAL BURNS. EYE: MECH
IRRIT. INHAL: FORMALDEHYDE IS HIGHLY IRRIT TO EYES & UPPER RESP TRACT.
(CHRONIC) FORMALDEHYDE RELEASE IN SM QTY DURING MELT PROCESSING IS
CLASSIFIED AS AN ANIMAL CARCINOGEN.
Carcinogenicity - NTP: NO
```

```
Carcinogenicity - IARC: NO Carcinogenicity - OSHA: NO
Explanation Carcinogenicity: NOT RELEVANT
Signs/Symptoms Of Overexp: SEE HEALTH HAZARDS.
Med Cond Aggravated By Exp: INDIVIDUALS WITH PREEXISTING DISEASES OF THE
LUNGS MAY HAVE INCREASED SUSCEPTIBILITY TO THE TOXICITY OF EXCESSIVE
EXPOSURE TO FORMALDEHYDE.
Emergency/First Aid Proc: IF EXPOSED TO FUMES FROM OVERHEATING OR
COMBUSTION, MOVE TO FRESH AIR. CONSULT A PHYSICIAN IF SYMPTOMS PERSIST.
FLUSH EYES WITH PLENTY OF WATER FOR AT LEAST 15 MINUTES. CONSULT A
PHYSICIAN IF SYMPTOMS PERSIST. IF MOLTEN POLYMER CONTACTS SKIN, COOL
RAPIDLY WITH COLD WATER. DO NOT ATTEMPT TO PEEL POLYMER FROM SKIN. OBTAIN
MEDICAL ATTN FOR THERMAL BURN.
______
                Precautions for Safe Handling and Use
______
Steps If Matl Released/Spill: SWEEP UP TO PREVENT A SLIPPING HAZARD.
Neutralizing Agent: NONE SPECIFIED BY MANUFACTURER.
Waste Disposal Method: INCINERATION OR LANDFILL IN COMPLIANCE WITH
FEDERAL, STATE AND LOCAL REGULATIONS.
Precautions-Handling/Storing: DRY STORAGE. KEEP CNTNRS CLSD TO PVNT CONTAM. OPEN CNTNRS ONLY IN WELL-VENT AREA. READ "SAFETY PREC TO OBSERVE
WHEN HANDLING MOLTEN (SEE OTHER PREC)
Other Precautions: HNDLG/STOR PREC: DELRIN ACETAL RESIN" E-49703 AND
"SAFETY PREC" IN MOLDING MANUAL E-09143, BEFORE USING DELRIN. AVOID
PROLONGED HEATING ABOVE MELTING POINT (178C).
______
                         Control Measures
______
Respiratory Protection: NIOSH/MSHA APPROVED RESPIRATOR APPROPRIATE FOR
EXPOSURE OF CONCERN (FP N) IF LOCAL EXHAUST VENTILATION DOES NOT KEEP FORMALDEHYDE CONC BELOW 1 PPM.
Ventilation: LOCAL EXHAUST AT PROCESSING EQUIPMENT.
Protective Gloves: PROTECTIVE GLOVES.
Eye Protection: CHEMICAL WORKERS GOGGLES (FP N).
Other Protective Equipment: LONG SLEEVE COTTON SHIRT AND LONG PANTS.
Work Hygienic Practices: NONE SPECIFIED BY MANUFACTURER.
Suppl. Safety & Health Data: FL PT METH: ASTM 1929-62. HAZ DECOMP PRODS: 1 PPM (8-HR TWA), AND A SHORT TERM EXPOSURE LIMIT OF 2 PPM (15 MINUTE).
______
                       Transportation Data
Trans Data Review Date: 91274
DOT PSN Code: ZZZ
DOT Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION
IMO PSN Code: ZZZ
IMO Proper Shipping Name: NOT REGULATED FOR THIS MODE OF TRANSPORTATION
IATA PSN Code: ZZZ
IATA Proper Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION
AFI PSN Code: ZZZ
AFI Prop. Shipping Name: NOT REGULATED BY THIS MODE OF TRANSPORTATION
Additional Trans Data: NOT REGULATED FOR TRANSPORTATION
______
                           Disposal Data
_______
______
                            Label Data
______
Label Required: YES
Technical Review Date: 20MAY91
Label Date: 20MAY91
Label Status: G
Common Name: DELRIN ACETAL RESIN, 550SA NC010
Signal Word: CAUTION!
Acute Health Hazard-Slight: X
Contact Hazard-Slight: X
Fire Hazard-Slight: X
Reactivity Hazard-None: X
Special Hazard Precautions: ACUTE: CAUSES RESPIRATORY TRACT IRRITATION.
AVOID BREATHING POWDER. KEEP CONTAINER CLOSED. USE WITH ADEQUATE
VENTILATION. CAUSES EYE IRRITATION. AVOID CONTACT WITH EYES. WASH
THOROUGHLY AFTER HANDLING. COMBUSTIBLE. KEEP AWAY FROM HEAT AND FLAME. CHRONIC: HEATING ABOVE 230C CAUSES THE FORMATION OF FORMALDEHYDE. REFER TO
Protect Eye: Y
Protect Skin: Y
Protect Respiratory: Y
Label Name: E I DUPONT DE NEMOURS & CO INC
Label Street: 1007 MARKET STREET
Label City: WILMINGTON
Label State: DE
```

## E I DUPONT -- DELRIN ACETAL RESIN, 550SA NC010

Label Zip Code: 19898 Label Country: US Label Emergency Number: 800-441-3637;800-424-9300(CHEMTREC)